

FIG. 3
(PRIOR ART)








FIG. 4 (PRIOR ART)








FIG. 9






FIG. 10






FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 22A




FIG. 22B




FIG. 21




FIG. 24







FIG. 23






FIG. 28A








FIG. 28B





Preventing of negative pressure






FIG. 32B




FIG. 33B




FIG. 32A




FIG. 33A




FIG. 34